#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 99.28

## WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-023558

Address: 333 Burma Road **Date Inspected:** 11-May-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai

**CWI Name:** Tian Lei, Liu Fa Wen, Chen Shig GWI Present: Yes No

**Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A

**Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG

#### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector R. Hernandez was present during the time noted above and conducted observations relative to the work being performed.

The QA Inspector randomly observed the following work in progress:

Bay Number 1

This inspector observed ZPMC personnel welding of components identified as Lift 13 & 14 lifting frame beam.

Bay Number 5

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. All components were as listed on NWIT notification no. 09094. The member(s) is/are identified as OBG Traveler Rail components identified below with the following identifying weld no.(s):

1. 3025TR1-001-001, 004, 007, 010, & 011.

Bay Number7

SAW welding of complete joint penetration welds located on Cantilever Box Bracket Assembly component

## WELDING INSPECTION REPORT

(Continued Page 2 of 3)

identified as BK3002-001 weld no.(s) 003 & 004. Welder is identified as welder no. 044771. The welding variables recorded by ZPMC QC identified as Liu Fa Wen appeared to comply with applicable WPS(s) WPS-B-T-2221-U4a-S-2.

Bay Number 8

This inspector did not observe any work being performed in this bay today.

Bay Number 9

ZPMC personnel heat straightening Orthotropic Box Girder (OBG) traveler rail member identified as 3016TR1-002 for weld(s) 001~016. Distortion appeared to be caused by welding. ZPMC Quality Control (QC) inspector identified as Mr. Chen Shigang was present to monitor the heat straightening process. The heat straightening appeared to comply with Heat Straightening Report (HSR) no. HSR(B)-10274.

This QA inspector performed VT of area described in NCR ZPMC-0953 the area previously repaired and accepted by ZPMC Quality Control personnel. This component was listed on NWIT notification no. 09098. The member(s) is/are identified as Service Platform #4 Railing component identified below:

1. 40' Collapsible End Flat Rack Container on which the service platform is placed is identified as CCLU940000, model 40'FR4/03A.

FCAW welding of complete joint penetration welds located on Traveler Rail component identified as 3009TR1-001 weld no.(s) 024. Welder is identified as welder no. 059446. The welding variables recorded by ZPMC QC identified as Chen Shigang appeared to comply with applicable WPS(s) WPS-B-T-2231-ESAB.

Unless otherwise noted above all items observed on this day appeared to be in general compliance with the applicable contract documents





#### **Summary of Conversations:**

Pertinent conversations are included in the body of the report.

# WELDING INSPECTION REPORT

(Continued Page 3 of 3)

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 1500-0042-02372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Rene	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer